

DOCUMENT NUMBER:

MTN-0071-24

ISSUE DATE:

2024-05

MOTOROLA SOLUTIONS TECHNICAL NOTIFICATION (MTN)

Title

MOTOTRBO R2 Power On Issue

Technology

MOTOTRBO R2

Severity Recommendation

High - Perform Immediately

Symptoms

Under very rare circumstances after turning the radio off, it may not be possible to turn the radio back on.

Models / System Releases / Kits / Datecodes Affected

Any MOTOTRBO R2 radios built with the R02.24.01.1002 version or older version.

When To Apply

Immediately

Resolution And Repair Procedure

Upgrade the MOTOTRBO R2 radio to the software version R02.24.01.3002 or newer.

Time To Implement/System Impact

Medium - time-consuming but no loss of functionalities

MOTOROLA SOLUTIONS TECHNICAL NOTIFICATION

ANY USE NOT APPROVED BY MOTOROLA SOLUTIONS IS PROHIBITED. This Motorola Technical Notification (MTN) is issued pursuant to Motorola's ongoing review of the quality, effectiveness, and performance of its products. The information provided in this bulletin is intended for use by trained, professional technicians only, who have the expertise to perform the service described in the MTN. Motorola disclaims any and all liability for product quality or performance if the recommendations in this MTN are not implemented, or not implemented in compliance with the instructions provided here. Implementation of these recommendations may be necessary for the product to remain compliant with applicable laws or regulations. Please be advised that failure to implement these recommendations in the manner instructed may also invalidate applicable warranties, or otherwise impact any potential contractual rights or obligations. MOTOROLA, MOTO, MOTOROLA SOLUTIONS, and the Stylized M Logo are trademarks or registered trademarks of Motorola Trademark Holdings, LLC and are used under license. All other trademarks are the property of their respective owners. © 2023 Motorola Solutions, Inc. All rights reserved.

DOCUMENT NUMBER: **MTN-0071-24**ISSUE DATE: **2024-05**

Software Parts Required

Name / SW version	Details / Part Number
MOTOTRBO_2.0_R0224013002_242104_Portable	MOTOTRBO R2 Radio Upgrade Package (ver R02.24.01.3002)
RM_2.146.122.0 or CPS2_2.146.122.0	Radio Management or CPS 2.0 Tool (Ver 2.146.122.0)

For assistance with this bulletin please contact your MSI Technical Support Centre at <https://motorolasolutions.com/support>

MOTOROLA SOLUTIONS TECHNICAL NOTIFICATION

ANY USE NOT APPROVED BY MOTOROLA SOLUTIONS IS PROHIBITED. This Motorola Technical Notification (MTN) is issued pursuant to Motorola's ongoing review of the quality, effectiveness, and performance of its products. The information provided in this bulletin is intended for use by trained, professional technicians only, who have the expertise to perform the service described in the MTN. Motorola disclaims any and all liability for product quality or performance if the recommendations in this MTN are not implemented, or not implemented in compliance with the instructions provided here. Implementation of these recommendations may be necessary for the product to remain compliant with applicable laws or regulations. Please be advised that failure to implement these recommendations in the manner instructed may also invalidate applicable warranties, or otherwise impact any potential contractual rights or obligations. MOTOROLA, MOTO, MOTOROLA SOLUTIONS, and the Stylized M Logo are trademarks or registered trademarks of Motorola Trademark Holdings, LLC and are used under license. All other trademarks are the property of their respective owners. © 2023 Motorola Solutions, Inc. All rights reserved.